

A2000 series alarming thermometer hygrometer measures temperature and humidity with various levels of high precision and alarming capability. Large LCD screen displays information such as real-time temperature and humidity, alarming, maximum or minimum record value, time, battery status etc. This meter have been widely used in laboratories, factories, medical warehouse and households.

This series products could set limit by keys and the devices will sound & light alarm when the data exceed. logger could deviation calibration , help to keep logger high accuracy. About external sensor models, external could expand as customers ask.



Features :

- LCD display Temp, Humidity, Time & Battery Status
- Sound & Light alarm while exceeding limit
- Switchable to C & F
- Desk-top placing or Wall Hanging.
- Deviation manual calibration



Technical Specifications

Display	: LCD screen display	
Temp measuring range	: -20°C ... 70°C	Resolution : 0.1°C
Temp accuracy	: ±0.5°C	
Humidity measuring range	: 0 - 100% RH	Resolution : 0.1%RH
Humidity accuracy	: ±5%RH	
Power supply	: 9V Battery	
Product size	: 135 x 124 x 35mm	
Net Weight	: 330g	
Package	: Main unit & Screw	